# ebaboard 0800

milling-parameters

n = revolutions
z = number of teeh
d = diameter
vf = feed rate

$$n = \frac{vc \cdot 1000}{d \cdot \pi} \quad [1/min]$$

$$vf = n \cdot fz \cdot z \quad [mm/min]$$

$$fz = \frac{vf}{z \cdot n} \quad [mm]$$

$$vc = -$$

*The specified tools and cutting parameters are for reference only. They may vary depending on the machine tool and part size*

| Technical Datas | Machining 1 | Machining 2 | Machining 3 | Machining 4 | Machining 5 | Machining 6 | Machining 7 |
|---|---|---|---|---|---|---|---|
| **Strategy** | **Roughing Z-Constant** | **Profile Roughing** | **Roughing Pocket** | **Roughing Residual Material Z-Constant** | **Finishing Face Milling** | **Finishing Z-Constant** | **Engraving** |
| **Type of milling cutter** | EMZ90 V22.042TH050 (1043249) | EBG V16.016AN140 | DHC Ø12 INOX | EBG V12.012AN120-C (6128023) | EBG V10.010AN120-C (6130578) | EBG R08.008AP100-C (9148824) | Airline Kugel (1121894) |
| **indexable inserts** | VCGT 220530-ALM (1069759) | WPB 16 AF 30 | - | WPB 12 CF 20 (6128107) | WPB 10 CF 10 (6129238) | WPR 08 DN (6131629) | - |
| **cutting diameter** [mm] | 42 | 25 | 12 | 12 | 10 | 8 | 2 |
| **number of tool cutting edges** | 3 | 2 | 3 | 2 | 2 | 2 | 2 |
| **Radius** [mm] | 3 | 13 | 1 | 2 | 1 | 4 | 1 |
| **Cutting Speed vc** [m/min] | 600 | 500 | 500 | 500 | 450 | 452 | 113 |
| **Revolutions n** [1/min] | 4547 | 6366 | 13262 | 13262 | 14323 | 18000 | 18000 |
| **Feed per Tooth fz** [mm] | 0,5 | 0,5 | 0,20 | 0,3 | 0,15 | 0,1 | 0,1 |
| **Feed Rate vf** [mm/min] | 6820 | 6366 | 7957 | 7957 | 4297 | 3600 | 3600 |
| **Axial Depth of Cut ap** [mm] | 5 | 2,5 | 10 | 2 | 0,5 | 0,2 | 0,5 |
| **Radial Depth of Cut ae** [mm] | 30 | 3 | 6 | 8 | 6 | 0,5 | 0 |
| **Runtime [min]** | 6 | 10 | 1 | 4 | 3,5 | 80 | 2 |
| **Dust Formation** | none | none | none | none | none | none | none |



ebalta Kunststoff GmbH | Erlbacher Straße 100 | 91541 Rothenburg o.d.T. - GERMANY | +49 9861 7007-0 | info@ebalta.com | www.ebalta.com